

Waste Site Reclassification Form

Date Submitted: 11/10/1999	Operable Unit(s): 200-SW-1	Control Number: 99-107
Originator:	Waste Site ID: 200-E-3	
Phone:	Type of Reclassification Action:	
	Rejected: <input checked="" type="radio"/>	
	No Action: <input type="radio"/>	
	Interim Closed Out: <input type="radio"/>	
	Closed Out: <input type="radio"/>	

This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed-out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.

Description of current waste site condition:

There are two reports of releases to the pit north of 241-AN Tank Farm. In 1991, it was reported that approximately 39 liters (10 gallons) of toluene was dumped inside the pit during the summer of 1984 or 1985. In 1995, two ICF Kaiser painters reported disposing of liquid paint waste to the ground inside the pit north of 241-AN Tank Farm. They recalled dumping approximately 95 liters (25 gallons) of liquid in one visit and another 95 liters (25 gallons) in a second visit. In 1996, a visit to the pit with one of the painters verified the pit north of 241-AN Tank Farm, just west of Canton Ave. as the dumping site location. He indicated the area in the southeast portion of the pit as the dump site. The effected area measured approximately 9 meters by 9 meters (30 feet by 30 feet).

Basis for reclassification:

The location description and release description for 200-E-3 match those for 200-E-10. Since 200-E-10 is listed in TPA Appendix C and 200-E-3 is not been listed in Appendix C, the duplicated information will be combined into 200-E-10. 200-E-3 should be Rejected because it is a duplicate entry in WIDS.

Steve Burkum	<i>Steve Burkum</i>	5/06/04
DOE Project Manager	Signature	Date
John B. Price	<i>John B. Price</i>	5/6/04
Ecology Project Manager	Signature	Date
N/A		
EPA Project Manager	Signature	Date